



TECHNICAL SERVICE BULLETIN

TSB#: 16-020

Job Code: 9801304

Flat Rate: 1hr

Date of Publication: August 2016

NOTE: This Technical Service Bulletin will be valid within (1) year from the original date of publication.

Action Required

Replace LCI Jack IT Bike Rack

Affected Units

2017 Hummingbird Travel Trailer

H13A 0051, 0059-0061, 0067,0069, 0076--0078,0086-0087,0089,0092--0094,
0105-0106

H13B 0051,0054,0073-0074,0079,0084,0099,0101,0103-0104,0109-0122,
0127-0129,0135,0140

H13C 0050

2017 Jay Feather Travel Trailer

H1 J20058, J30100-0101,0109, J40056 JC0062-0063
JL0063-0064, 0078 JM0077

2017 White Hawk Travel Trailer

H1 450069, 460071-460073, 4B0114, 4C0084,0087 4F0050
4T0063-0065 4U0065,0080

PARTS KIT 16-020JT

Parts kit shipped direct for affected units in
Dealers' Inventory - **ONLY** retail sold units require
order

- 1 LCI Jack-IT Bike Rack

INSTRUCTIONS

Please follow LCI installation instructions provided

**PLEASE DO NOT RETURN THE ORIGINAL BIKE RACK AND DO NOT INSTALL ON OTHER RVs.
PLEASE DESTROY BIKE RACK REMOVED UNDER THIS BULLETIN.**



This manual is provided courtesy of **RV Tech Cheat Sheet**



Professional resources for the whole RV industry — free.

We put manuals, wiring diagrams and hard-won tech knowledge in every technician's hands, so repairs get done right the first time, techs work faster, and RV owners everywhere get better service.



rvtechcheatsheet.com/manuals

Find thousands more RV manuals, wiring diagrams and parts lists

RV techs: share fixes, ask questions and learn from each other.

Join our free Facebook group →



Follow proper safety practices. If in doubt, consult a professional RV technician.