



U.S. Department of Transportation
**National Highway Traffic Safety
Administration**

1200 New Jersey Avenue SE
Washington, DC 20590

October 5, 2017

Mr. Craig Biazio
National Warranty Manager
REV Recreation Group
1010 Commerce Drive
PO Box 1007
Decatur, IN 46733

NEF-150MR
17V-584

Subject: Battery Tray Separation Leaking Battery Acid

Dear Mr. Biazio:

This letter serves to acknowledge REV Recreation Group's notification to the National Highway Traffic Safety Administration (NHTSA) of a safety recall which will be conducted pursuant to Federal law for the product(s) listed below. Please review the following information to ensure that it conforms to your records as this information is being made available to the public. If the information does not agree with your records, please contact us immediately to discuss your concerns.

Makes/Models/Model Years:

FLEETWOOD/BOUNDER/2013-2015
FLEETWOOD/SOUTHWIND/2013-2016

Mfr's Report Date: September 20, 2017

NHTSA Campaign Number: 17V-584

Components:

ELECTRICAL SYSTEM:BATTERY

Potential Number of Units Affected: 2,532

Problem Description:

REV Recreation Group (REV) is recalling certain 2013-2015 Fleetwood Bounder and 2013-2016 Fleetwood Southwind recreational vehicles. The welds attaching the battery tray may be insufficient. As a result, the tray may separate from underneath the chassis.

Consequence:

An unsecured battery tray can cause a battery acid leak or an electrical short, increasing the risk of a fire or injury.

Remedy:

REV will notify owners, and dealers will inspect the battery tray, and install fasteners, if necessary, to secure the battery tray, free of charge. The recall is expected to begin November 20, 2017. Owners may contact REV customer service at 1-800-509-3417. REV's number for this recall is 170914REV.

Notes:

Owners may also contact the National Highway Traffic Safety Administration Vehicle Safety Hotline at 1-888-327-4236 (TTY 1-800-424-9153), or go to www.safercar.gov.

Please be reminded of the following requirements:

You are required to submit a draft owner notification letter to this office no less than five days prior to mailing it to the customers. Also, copies of all notices, bulletins, dealer notifications, and other communications that relate to this recall, including a copy of the final owner notification letter and any subsequent owner follow-up notification letter(s), are required to be submitted to this office no later than 5 days after they are originally sent (if they are sent to more than one manufacturer, distributor, dealer, or purchaser/owner).

As stated in Part 573.7, submission of the first of six consecutive quarterly status reports is required within one month after the close of the calendar quarter in which notification to purchasers occurs. Therefore, the first quarterly report will be due on, or before, 30 days after the close of the calendar quarter.

Your contact for this recall will be Michelle Rice who may be reached by phone at (202) 366-1060, or by email at michelle.rice@dot.gov or through the office email at rmd.odi@dot.gov. We look forward to working with you.

Sincerely,

A handwritten signature in black ink, appearing to read "J. Timian", with a horizontal line extending to the right.

Jennifer Timian
Chief, Recall Management Division
Office of Defects Investigations
Enforcement



This manual is provided courtesy of **RV Tech Cheat Sheet**



Professional resources for the whole RV industry — free.

We put manuals, wiring diagrams and hard-won tech knowledge in every technician's hands, so repairs get done right the first time, techs work faster, and RV owners everywhere get better service.



rvtechcheatsheet.com/manuals

Find thousands more RV manuals, wiring diagrams and parts lists

RV techs: share fixes, ask questions and learn from each other.

Join our free Facebook group →



Follow proper safety practices. If in doubt, consult a professional RV technician.