

Actuator Motor Identification

In light of Norco's efforts to secure a reliable parts supply for our OEM customers, we have multi sourced our linear actuators for our "through-frame" slide-outs. Although our two linear actuator assemblies are completely interchangeable, the specific motors of the assemblies are not. If a replacement motor is needed, rather than replacing an entire actuator assembly the actuator motor ONLY can be identified using this guide. Please match the original motor to one of the three motors below to assure a proper replacement will be ordered. You may also provide the BAL Chassis S/N to a member of our technical support team, and they will assist you in locating the correct motor part number

40" Actuator motor, 9,500 RPM, Black, P/N: 20900114.

24" Actuator motor, 5,800 RPM, Black, P/N: 20900115.



40" Actuator motor, 9,000 RPM, Grey, P/N: 21700061.





This manual is provided courtesy of **RV Tech Cheat Sheet**



Professional resources for the whole RV industry — free.

We put manuals, wiring diagrams and hard-won tech knowledge in every technician's hands, so repairs get done right the first time, techs work faster, and RV owners everywhere get better service.



rvtechcheatsheet.com/manuals

Find thousands more RV manuals, wiring diagrams and parts lists

RV techs: share fixes, ask questions and learn from each other.

Join our free Facebook group →



Follow proper safety practices. If in doubt, consult a professional RV technician.