






Frame Rail Profile

Bottom Flange
of Rail

Vertical Web

⚠ WARNING

When lifting an RV with a floor jack, it is critical to position the jack directly under the vertical web of the frame rail. Lifting and/or supporting the RV under the bottom lip (or flange) of the rail can result in damage to the frame and/or RV and create an unsafe working environment.



This manual is provided courtesy of **RV Tech Cheat Sheet**



Professional resources for the whole RV industry — free.

We put manuals, wiring diagrams and hard-won tech knowledge in every technician's hands, so repairs get done right the first time, techs work faster, and RV owners everywhere get better service.



rvtechcheatsheet.com/manuals

Find thousands more RV manuals, wiring diagrams and parts lists

RV techs: share fixes, ask questions and learn from each other.

Join our free Facebook group →



Follow proper safety practices. If in doubt, consult a professional RV technician.