



IMPORTANT SAFETY RECALL

NHTSA Safety Recall: 16E-088

Date: January __, 2017

VIA EMAIL & OVERNIGHT DELIVERY

Dear Customer:

This Notice is sent to you in accordance with the requirements of the United States National Traffic and Motor Vehicle Safety Act.

REASON FOR THIS RECALL

Lippert Components, Inc. ("LCI") has conducted a thorough investigation and decided that a defect which relates to motor vehicle safety exists in vehicles equipped with certain LCI axles. There may be loose brake flange nuts on the roadside brake. If the brake nuts are loose the brake could potentially spin in the drum breaking the magnet wire possibly causing the brake to not engage and/or lock up posing a risk of personal injury or property damage. Our records indicate that your company purchased axle assemblies that are the subject of this recall. The axles sold to you that are subject to the recall are described in detail in a spreadsheet included with this notice. **If these axles are still in your inventory, you must not sell or install these units. It is a violation of federal law to sell any of the listed axles covered by this recall until the defect is remedied. The Brake Flange Nut Recall Repair Instructions which directs you on how to properly inspect and repair the brakes are enclosed with this letter.**

WHAT WE WILL DO

LCI will reimburse you for the inspection and to adjust the brake flange nuts, if necessary, on the affected axles within the recall population that are installed on your vehicles. LCI will also reimburse you for the labor charged by your dealers at the flat rate of 0.8 hours to inspect and repair the flange nuts.

WHAT YOU SHOULD DO

If you have any questions you may contact LCI's Customer Service department at 574-537-8900 or customerservice@lci1.com. Please refer to the enclosed listing of axle serial numbers to determine if you have any affected axles. If you had appropriate repairs completed prior to receipt of this recall notice, and if you incurred any direct cost in connection with such repair, you may be eligible for reimbursement from LCI by contacting the Customer Service department.

If after contacting LCI's Customer Service you are still not satisfied we have done our best to remedy this situation, you may also submit a written complaint to: Administrator, National Highway Traffic Safety Administration, 1200 New Jersey Avenue SE, Washington, DC 20590. You may call the toll-free Vehicle Safety Hotline at 1-888-327-4236 (TTY: 1-800-424-9153; or go to <http://www.safercar.gov>.) Federal regulations require that any vehicle lessor receiving this recall notice must forward a copy of this notice to the lessee within ten days.

We regret any inconvenience this action may cause you. As we are sure you will appreciate, the safety and quality of our products are of the utmost importance to us. Thank you for your attention and cooperation in this matter.

Sincerely,

Lippert Components, Inc.



This manual is provided courtesy of **RV Tech Cheat Sheet**



Professional resources for the whole RV industry — free.

We put manuals, wiring diagrams and hard-won tech knowledge in every technician's hands, so repairs get done right the first time, techs work faster, and RV owners everywhere get better service.



rvtechcheatsheet.com/manuals

Find thousands more RV manuals, wiring diagrams and parts lists

RV techs: share fixes, ask questions and learn from each other.

Join our free Facebook group →



Follow proper safety practices. If in doubt, consult a professional RV technician.