

SLIDE-OUTS

Fig. 1 - Venture & Toula Actuator





Fig. 2 - Tuson Actuator



NOTE: Toula actuators and motors can be replaced by Venture.

Part #	Description
125802	Tuson 18:1
132682	Venture 18:1
136373	Venture 28:1

Fig. 3 - Tuson



Fig. 4 - Tuson





Fig. 5 - Venture & Toula



Part #	Actuator & Motor (18:1)	Size
119128	Venture	24"
122747	Venture	32"
119129	Venture	40"
145595	Venture Actuator Only	40"
145185	Tuson	24"
131903	Tuson	40"
145596	Tuson Actuator Only	40"

As a supplier of components to the RV industry, safety, education and customer satisfaction are our primary concerns. Should you have any questions, please do not hesitate to contact us at (574) 537-8900 or by email at customerservice@lci1.com. Self-help tips, technical documents, product videos and a training class schedule are available at www.lci1.com or by downloading the MyLCI app.



This manual is provided courtesy of **RV Tech Cheat Sheet**



Professional resources for the whole RV industry — free.

We put manuals, wiring diagrams and hard-won tech knowledge in every technician's hands, so repairs get done right the first time, techs work faster, and RV owners everywhere get better service.



rvtechcheatsheet.com/manuals

Find thousands more RV manuals, wiring diagrams and parts lists

RV techs: share fixes, ask questions and learn from each other.

Join our free Facebook group →



Follow proper safety practices. If in doubt, consult a professional RV technician.