




Tip Sheet #12002

Pump Harness Fuse Update Spring Return Hydraulic Leveling

© PowerGear 1/08 Tip Sheet #12002 Rev. 0A

Spring Return Hydraulic Leveling Pump Harness Fuse Update

Introduction




The fuse in the 1510000064 pump harness has been changed from a 5 amp to 10 amp fuse.

Condition: If, after attempting to operate the Power Gear Spring Return leveling system, the “Low Voltage” LED on the touch pad remains ON and no other buttons are functional, except on/off button, then the 5 amp pump harness fuse has blown.

Replace the fuse with a 10 amp mini fuse.

Winnebago Industries effected units were built/manufactured between June of 2007 through August of 2007. Units manufactured after that time period were equipped with the 10 amp fuse.



WARNING

Extreme caution must be used when working on hydraulic leveling jacks. Avoid all pinch points and do not use the leveling system to lift the coach wheels off the ground. Failure to heed all warnings may result in serious injury or death.





This manual is provided courtesy of **RV Tech Cheat Sheet**



Professional resources for the whole RV industry — free.

We put manuals, wiring diagrams and hard-won tech knowledge in every technician's hands, so repairs get done right the first time, techs work faster, and RV owners everywhere get better service.



rvtechcheatsheet.com/manuals

Find thousands more RV manuals, wiring diagrams and parts lists

RV techs: share fixes, ask questions and learn from each other.

Join our free Facebook group →



Follow proper safety practices. If in doubt, consult a professional RV technician.