

STRINGS ADJUSTMENT TENSION MANUAL

OBLO 2.0

Plant 310




*Whenever, wherever,
we make your experience better.*

TI-436 CCD-0006481

Rev. 06.29.2022


INTRODUCTION

In the groove of the blind mount there are 4 adjustment plates.
The plates are used to adjust the wire tension of the fabric in the opposite side.




TENSION ADJUSTMENT


- Detect which fabric needs to be adjusted.
- Place its handle in closed position and hold it.
- Slightly unscrew the screw in the opposite side until the wire clamp plate is free to move.
- Move the wire clamp plate as shown in the picture to increase or decrease the string tension.




TENSION ADJUSTMENT



If the handle is moved forward on the left, it means that the tension of the ropes on the left side is too high. Reduce the tension of the ropes on the left side.



If the handle is moved forward on the right, it means that the tension of the ropes on the right side is too high. Reduce the tension of the ropes on the right side.



When the handle is in the horizontal position, it means that the string tension is correct. Screw the screws to lock the strings in the desired position.

If too much force is required to move the handle, loosen the cords in both side slightly.



If the rope tension is too high, the handle will be more difficult to move. If the rope tension is too low, the handle may get stuck on the way.



This manual is provided courtesy of **RV Tech Cheat Sheet**



Professional resources for the whole RV industry — free.

We put manuals, wiring diagrams and hard-won tech knowledge in every technician's hands, so repairs get done right the first time, techs work faster, and RV owners everywhere get better service.



rvtechcheatsheet.com/manuals

Find thousands more RV manuals, wiring diagrams and parts lists

RV techs: share fixes, ask questions and learn from each other.

Join our free Facebook group →



Follow proper safety practices. If in doubt, consult a professional RV technician.