



T.I.P. Troubleshooting Information on Power Gear

FUSE REPLACEMENT FOR 500457 CONTROL BOX.

NOTE: THIS IS FOR R.V.'S MANUFACTURED AFTER 8-1-98.


ALL FUSES USED IN THE 500457 CONTROL BOX ARE AUTOMOTIVE 3 AMP, 32 VOLT, VIOLET COLORED FAST ACTING FUSES.

LEFT VALVE SOLENOID- 3 AMP FUSE
RIGHT VALVE SOLENOID- 3 AMP FUSE
DUMP VALVE SOLENOID- 3 AMP FUSE
FRONT VALVE SOLENOID- 3 AMP FUSE

REMOVE: TO REMOVE FUSE, USE FUSE PULLER OR NEEDLE NOSE PLIERS AND PULL FUSE STRAIGHT OUT.

INSTALL: TO INSTALL FUSE, USE FUSE PULLER, NEEDLE NOSE PLIERS, OR YOUR HAND TO INSERT THE FUSE MAKING SURE PINS ON FUSE ENTER RECEPTACLE CORRECTLY.

Part # 500457





This manual is provided courtesy of **RV Tech Cheat Sheet**



Professional resources for the whole RV industry — free.

We put manuals, wiring diagrams and hard-won tech knowledge in every technician's hands, so repairs get done right the first time, techs work faster, and RV owners everywhere get better service.



rvtechcheatsheet.com/manuals

Find thousands more RV manuals, wiring diagrams and parts lists

RV techs: share fixes, ask questions and learn from each other.

Join our free Facebook group →



Follow proper safety practices. If in doubt, consult a professional RV technician.