



Service Bulletin

© Copyright PowerGear, Issued: 4-20-2011

#82-L0504, Rev. 0A 4-20-2011

Hydraulic Hoses used with leveling systems

A number of RV owners have expressed concerns about bubbles appearing on the outer surfaces of hydraulic hoses that operate their leveling jacks. This bulletin has been issued to confirm that such bubbles on the hoses are purely cosmetic, and merely result from occasional accumulations of vapor released by the hydraulic fluid, which are able to pass through the hose's body, and are then confined by the outer surface. The hydraulic fluid itself is not passing through the hose body, and is not leaking. Accordingly, the bubbling is not a safety issue, and will not affect the operation of the leveling system. The hoses used with the leveling systems are fully tested, and meet or exceed the SAE J343 and SAE J517 standards for 100R7 type hydraulic hose. Power Gear along with its hose supplier has tested hoses containing bubbles. Independent test results have confirmed the bubbled hoses continue to meet our leveling system requirements, and pose no safety or performance concerns. The bubbling of these hoses is therefore not a failure. As a matter of good will, Power Gear has honored requests for the replacement of bubbled hoses within the warranty terms, we cannot participate in any post-warranty claims in regards to this cosmetic issue.





This manual is provided courtesy of **RV Tech Cheat Sheet**



Professional resources for the whole RV industry — free.

We put manuals, wiring diagrams and hard-won tech knowledge in every technician's hands, so repairs get done right the first time, techs work faster, and RV owners everywhere get better service.



rvtechcheatsheet.com/manuals

Find thousands more RV manuals, wiring diagrams and parts lists

RV techs: share fixes, ask questions and learn from each other.

Join our free Facebook group →



Follow proper safety practices. If in doubt, consult a professional RV technician.