

JAYCOMMAND

powered by  **BM PRO**

POWERING YOUR ADVENTURES.


HELP GUIDE

AUTO HITCH HEIGHT


JAYCOMMAND
powered by  **BM PRO**



CONTROLLER



NODE



APP



SWITCH

SYSTEM COMPONENTS

Auto Hitch Height Button on LCI mini Touch pad not functioning?

This may occur when trying to initiate the auto hitch height feature from outside mini touch pad using BMPRO firmware 1.3.3 and earlier.

1. Update the APP to update the firmware
2. The firmware will be available on the 10/24/19
3. Follow the Help guide, **Updating the JAYCOMMAND App, Firmware & BYOD**



BMPRO
821 E. Windsor Ave, Unit 1
Elkhart, IN 46514
service@teambmprompro.com



This manual is provided courtesy of **RV Tech Cheat Sheet**



Professional resources for the whole RV industry — free.

We put manuals, wiring diagrams and hard-won tech knowledge in every technician's hands, so repairs get done right the first time, techs work faster, and RV owners everywhere get better service.



rvtechcheatsheet.com/manuals

Find thousands more RV manuals, wiring diagrams and parts lists

RV techs: share fixes, ask questions and learn from each other.

Join our free Facebook group →



Follow proper safety practices. If in doubt, consult a professional RV technician.