



WARRANTY LABOR REIMBURSEMENT RATES

Flat Rate Labor Allowance	
<u>MaxxFan Deluxe</u>	
Change Operator	30 Min.
Change Fan Motor	30 Min.
Change Lift Motor	30 Min.
Change Fan Blade	15 Min.
Change Lid	45 Min.
Change Printed Circuit Board	45 Min.
Change Garnish Ring	15 Min.
Replace Complete MaxxFan	30 Min.
Replace Handheld Remote (HHR)	0 Min.
Replace Wall Control	15 Min.
Replace Rain Sensor	30 Min.

Flat Rate Labor Allowance	
<u>MaxxFan Standard</u>	
Change Operator	30 Min.
Change Fan Motor	30 Min.
Change Lift Motor	30 Min.
Change Fan Blade	15 Min.
Change Lid	30 Min.
Change Printed Circuit Board	45 Min.
Change Garnish Ring	15 Min.
Replace Complete MaxxFan	1 Hour
Replace Handheld Remote (HHR)	0 Min.
Replace Wall Control	15 Min.
Replace Rain Sensor	30 Min.

MaxxAir Ventilation Solutions
Airxcel RV Group
P.O. Box 4020
Wichita, KS 67204
316-832-3400



This manual is provided courtesy of **RV Tech Cheat Sheet**



Professional resources for the whole RV industry — free.

We put manuals, wiring diagrams and hard-won tech knowledge in every technician's hands, so repairs get done right the first time, techs work faster, and RV owners everywhere get better service.



rvtechcheatsheet.com/manuals

Find thousands more RV manuals, wiring diagrams and parts lists

RV techs: share fixes, ask questions and learn from each other.

Join our free Facebook group →



Follow proper safety practices. If in doubt, consult a professional RV technician.