

Quick Goose II & Folding Ball Gooseneck Hitches

Make / Model	Style	Years	Footnotes	Quick Goose II Hitch#	Folding Ball Hitch#	Bracket#
Chevrolet						
Silverado 1500	--	99 - 06	Z	60630	61652	60652
Silverado 1500 Classic	--	07 - 07	Z	60630	61652	60652
Silverado 1500 HD Classic	--	07 - 07	Z	60630	61652	60652
Silverado 2500	--	99 - 04	Z	60630	61652	60652
Silverado 2500 HD	--	01 - 10	4, Z	60630	61652	60652
Silverado 3500 HD	--	01 - 10	4, Z	60630	61652	60652
	Old body	99 - 00	Z	60630	61652	60631
Full Size Pickups	Excluding 34" frame (O.D.)	88 - 98	Z	60630	61652	60631
Dodge						
Ram 1500	--	02 - 08	1, 2	60640	--	60659
Ram 1500	--	94 - 01	Z	60640	--	60635
Ram 2500	--	03 - 10	1, 2, 5, Z	--	61652	60661
	--	94 - 02	5, Z	60640	--	60635
Ram 3500	--	03 - 10	1, 2, 5, Z	--	61652	60661
	--	94 - 02	5, Z	60640	--	60635
Ford						
F-150	--	04 - 14	Z	60630	61652	60641
	--	97 - 03	Z	60630	61652	60637
	--	80 - 96	1, Z	60630	61652	60636
	Heritage Edition	04 - 04	Z	60630	61652	60637
F-250	New body	97 - 03	Z	60630	61652	60637
	Old body	80 - 98	--	60630	61652	60636
F-250 & F-350 Super Duty	--	11 - 16	3, Z	60630	61652	60644
	--	99 - 10	3, Z	60640	--	60644
	--	99 - 10	3, Z	60640	--	60643*
F-350	Excluding overload springs	80 - 98	Z	60630	61652	60636
	--	80 - 98	--	60630	61652	60636
F-450 Super Duty	Excluding cab & chassis	08 - 12	3, Z	60640	--	60644
	--	08 - 10	3, Z	60640	--	60643*
GMC						
Sierra 1500	--	99 - 06	Z	60630	61652	60652
Sierra 1500 Classic	--	07 - 07	Z	60630	61652	60652
Sierra 1500 HD Classic	--	07 - 07	Z	60630	61652	60652
Sierra 2500	--	99 - 04	Z	60630	61652	60652
Sierra 2500 HD	--	01 - 10	4, Z	60630	61652	60652
Sierra 3500 HD	--	01 - 10	4, Z	60630	61652	60652
	Old body	99 - 00	Z	60630	61652	60631
Full Size Pickups	Excluding 34" frame (O.D.)	88 - 98	Z	60630	61652	60631
Ram						
2500	--	11 - 13	1, 2, 5, Z	--	61652	60661
3500	--	11 - 12	1, 2, 5, Z	--	61652	60661

*While Supplies Last

Footnotes

- 1 - Passenger-side wheel well must be notched for frame rail access
 - 2 - Parking brake cable bracket may require relocation
 - 3 - Exhaust may have to be permanently lowered on 2005 and newer models
 - 4 - Vacuum canister requires relocation (kit included)
 - 5 - Do not invert ball with heavy loads on two-wheel drive models
- Z - No frame drilling required
- All Models: Brake, fuel, and electrical lines may need to be loosened or repositioned. Heat shield requires modification or removal.



This manual is provided courtesy of **RV Tech Cheat Sheet**



Professional resources for the whole RV industry — free.

We put manuals, wiring diagrams and hard-won tech knowledge in every technician's hands, so repairs get done right the first time, techs work faster, and RV owners everywhere get better service.



rvtechcheatsheet.com/manuals

Find thousands more RV manuals, wiring diagrams and parts lists

RV techs: share fixes, ask questions and learn from each other.

Join our free Facebook group →



Follow proper safety practices. If in doubt, consult a professional RV technician.