




Doing Our Best to Provide You the Best

8C010300, Rev AB

6/19/19

CBX SUSPENSION

Shock Limit Strap



ATTENTION: The nylon shock limit straps and cable ties are **NOT** for shipping purposes and must remain on the shock to prevent damage by over-extending.

NOTE: Cable ties must remain intact while trailer is in service. When replacing a worn or damaged shock strap, cable ties also need to be replaced and re-installed. (Recommended cable ties should be 11.5" long, UV resistant, and have a tensile strength of 120 lbs.)



This manual is provided courtesy of **RV Tech Cheat Sheet**



Professional resources for the whole RV industry — free.

We put manuals, wiring diagrams and hard-won tech knowledge in every technician's hands, so repairs get done right the first time, techs work faster, and RV owners everywhere get better service.



rvtechcheatsheet.com/manuals

Find thousands more RV manuals, wiring diagrams and parts lists

RV techs: share fixes, ask questions and learn from each other.

Join our free Facebook group →



Follow proper safety practices. If in doubt, consult a professional RV technician.