



T.I.P. Troubleshooting Information on Power Gear


FUSE REPLACEMENT FOR SEMI-AUTOMATIC TOUCH PAD

Note: This is for R.V.'s manufactured after 21-01-'95

XF1 = Remote Jacks down light fuse 1.6 AMP.

Note: To remove fuse use a needle nose pliers and pull fuse straight out. To install use needle nose pliers to insert fuse, making sure pins on fuse enter the receptical correctly.

View shown is back of semi-automatic touch pad.





This manual is provided courtesy of **RV Tech Cheat Sheet**



Professional resources for the whole RV industry — free.

We put manuals, wiring diagrams and hard-won tech knowledge in every technician's hands, so repairs get done right the first time, techs work faster, and RV owners everywhere get better service.



rvtechcheatsheet.com/manuals

Find thousands more RV manuals, wiring diagrams and parts lists

RV techs: share fixes, ask questions and learn from each other.

Join our free Facebook group →



Follow proper safety practices. If in doubt, consult a professional RV technician.