





WIRING OF THE NEUTRAL
SAFETY SWITCH ON "93"
MODEL YEAR CHASSIS



WIRING OF THE NEUTRAL SAFETY SWITCH ON "94" MODEL YEAR CHASSIS

NOTE:

FORD CHANGED IT'S WIRING OF THE 8 PIN PLUG IN '94. THE RED W/BUE WIRE MOVED FROM PIN 6 TO PIN 5. THE MIL. CYL. WIRE OR FLEETWOOD WIRE (WHICH EVER IS USED) WILL REMAIN SPLICED TO THE RED W/BUE WHERE EVER IT'S LOCATION MAY BE.



This manual is provided courtesy of **RV Tech Cheat Sheet**



Professional resources for the whole RV industry — free.

We put manuals, wiring diagrams and hard-won tech knowledge in every technician's hands, so repairs get done right the first time, techs work faster, and RV owners everywhere get better service.



rvtechcheatsheet.com/manuals

Find thousands more RV manuals, wiring diagrams and parts lists

RV techs: share fixes, ask questions and learn from each other.

Join our free Facebook group →



Follow proper safety practices. If in doubt, consult a professional RV technician.