




QUICKBITE COUPLERS AND COMPONENTS

TOWING



Callout	Part #	Description
A	135430	50 Degree Coupler; 2 $\frac{5}{16}$ " (14,000 lbs.)
B	119096	5104 - 24; CI4 A-Frame 2 $\frac{5}{16}$ " 13,000# Shelby Coupler (OBSOLETE)
C	212715	QuickBite Coupler Model 7000 SS; 1 $\frac{7}{8}$ " - 2" Ball; 10,000# (OBSOLETE)
	2127192	QuickBite Coupler Model 7007 XT; 1 $\frac{7}{8}$ " - 2" Ball; 10,000# (OBSOLETE)
	2127182	QuickBite Coupler Model 7007; 1 $\frac{7}{8}$ " - 2" Ball; 10,000# (OBSOLETE)



This manual is provided courtesy of **RV Tech Cheat Sheet**



Professional resources for the whole RV industry — free.

We put manuals, wiring diagrams and hard-won tech knowledge in every technician's hands, so repairs get done right the first time, techs work faster, and RV owners everywhere get better service.



rvtechcheatsheet.com/manuals

Find thousands more RV manuals, wiring diagrams and parts lists

RV techs: share fixes, ask questions and learn from each other.

Join our free Facebook group →



Follow proper safety practices. If in doubt, consult a professional RV technician.