

TOWING PRODUCTS

Fig. 1



The Reese Goose Box (305094) (Fig. 1) is an acceptable aftermarket replacement for LCI pin boxes 1621* and 1716. When installed properly, this does NOT void the Lippert Limited Frame Warranty.

NOTE: The Reese Goose Box (305094) is a replacement for the Lippert Pin Box 1621* and 1716 only. Replacing pin boxes 1621* or 1716 with any other gooseneck except Reese Goose Box (305094) will void the Lippert Limited Frame Warranty.

***NOTE:** This does not include the 1621HD.

NOTE: Reese Goose Box (305094) cannot be installed on the Space Saver Upper Deck chassis.

As a supplier of components to the RV industry, safety, education and customer satisfaction are our primary concerns. Should you have any questions, please do not hesitate to contact us at (574) 537-8900 or by email at customerservice@lci1.com. Self-help tips, technical documents, product videos and a training class schedule are available at lippert.com or by downloading the MyLCI app.



This manual is provided courtesy of **RV Tech Cheat Sheet**



Professional resources for the whole RV industry — free.

We put manuals, wiring diagrams and hard-won tech knowledge in every technician's hands, so repairs get done right the first time, techs work faster, and RV owners everywhere get better service.



rvtechcheatsheet.com/manuals

Find thousands more RV manuals, wiring diagrams and parts lists

RV techs: share fixes, ask questions and learn from each other.

Join our free Facebook group →



Follow proper safety practices. If in doubt, consult a professional RV technician.