

Purpose

This document provides the procedures for replacing an improperly-functioning cupholder ring for theater seating double tap cupholders.

NOTE: This procedure is for the retail version of the double tap cupholders. The OEM trim ring replacement is different than the process described in this document.

Safety

Read and understand all instructions before installing or operating this product. Adhere to all safety labels. This manual provides general instructions. Many variables can change the circumstances of the instructions, i.e., the degree of difficulty, operation and ability of the individual performing the instructions. This manual cannot begin to plot out instructions for every possibility, but provides the general instructions, as necessary, for effectively interfacing with the device, product or system. Failure to correctly follow the provided instructions may result in death, serious personal injury, severe product and/or property damage, including voiding of the LCI limited warranty.

Resources Required

- Cordless or electric drill or screwdriver
- #2 Phillips driver bit
- Optional Phillips screwdriver
- Replacement cupholder kit: PN 729242 blue lights, PN 729243 white lights

Replacement Procedure

1. Lift out cupholder (Fig. 1) and set aside.
2. Using a #2 Phillips bit or a Phillips screwdriver, remove the three screws from the cupholder ring (Fig. 2). Save the screws for reinstallation.
3. Remove cupholder ring (Fig. 3).

Fig. 1



Fig. 2





Fig. 3



FURNITURE

4. Follow the wires underneath the arm and disconnect the ring (Fig. 4).
5. Plug in the end of the new ring (Fig. 5).

Fig. 4



Fig. 5



6. Replace ring in seat arm cavity (Fig. 6) while making sure the wires are extended toward the back of the seat.
7. Secure the cupholder ring by slowly and gently reinstalling the three screws which secure the ring to the seat arm (Fig. 7).

NOTE: Do not insert screws straight into the seat arm. The screws are angled about 30 degrees when they are reinstalled (Fig. 7).

8. Place cupholder in ring.

Fig. 6



Fig. 7



As a supplier of components to the RV industry, safety, education and customer satisfaction are our primary concerns. Should you have any questions, please do not hesitate to contact us at (574) 537-8900 or by email at customerservice@lci1.com. Self-help tips, technical documents, product videos and a training class schedule are available at lippert.com or by downloading the MyLCI app.



This manual is provided courtesy of **RV Tech Cheat Sheet**



Professional resources for the whole RV industry — free.

We put manuals, wiring diagrams and hard-won tech knowledge in every technician's hands, so repairs get done right the first time, techs work faster, and RV owners everywhere get better service.



rvtechcheatsheet.com/manuals

Find thousands more RV manuals, wiring diagrams and parts lists

RV techs: share fixes, ask questions and learn from each other.

Join our free Facebook group →



Follow proper safety practices. If in doubt, consult a professional RV technician.