



AWNINGS

Product Information

Occasionally damage may occur to the awning fabric on products. If damage occurs causing a pin hole or a rip in the fabric, it can be corrected without requiring replacement of the product. In place of ordering a completely new item, a quick and inexpensive repair can be made to correct the damage. The photos show examples of the type of damage which can be repaired by the approved contractor (listed below) when needed.

Fabric Pin Hole Damage**Fabric Rip Damage****Approved Contractor For Repairing LCI Products:**

1. Fibernew
PH: 1-800-345-2951
www.fibernew.com

As a supplier of components to the RV industry, safety, education and customer satisfaction are our primary concerns. Should you have any questions, please do not hesitate to contact us at (574) 537-8900 or by email at customerservice@lci1.com. Self-help tips, technical documents, product videos and a training class schedule are available at lci1.com or by downloading the MyLCI app.



This manual is provided courtesy of **RV Tech Cheat Sheet**



Professional resources for the whole RV industry — free.

We put manuals, wiring diagrams and hard-won tech knowledge in every technician's hands, so repairs get done right the first time, techs work faster, and RV owners everywhere get better service.



rvtechcheatsheet.com/manuals

Find thousands more RV manuals, wiring diagrams and parts lists

RV techs: share fixes, ask questions and learn from each other.

Join our free Facebook group →



Follow proper safety practices. If in doubt, consult a professional RV technician.