



**LIPPERT**
COMPONENTS®

Product Information

Occasionally damage may occur to the vinyl covering of products. If damage occurs causing a hole, rip or flaking in the vinyl, it can be corrected without requiring replacement of the product. In place of ordering a completely new item, a quick and inexpensive repair can be made to correct the damage. The photos show examples of the type of damage which can be repaired by the approved contractors (listed below) when needed.

Vinyl Flaking**Vinyl Rip**

Approved Contractors For Repairing LCI Products:

1. Creative Colors International
PH: 1-800-933-2656
www.creativecolorsintl.com
2. Fibernew
PH: 1-800-345-2951
www.fibernew.com



This manual is provided courtesy of **RV Tech Cheat Sheet**



Professional resources for the whole RV industry — free.

We put manuals, wiring diagrams and hard-won tech knowledge in every technician's hands, so repairs get done right the first time, techs work faster, and RV owners everywhere get better service.



rvtechcheatsheet.com/manuals

Find thousands more RV manuals, wiring diagrams and parts lists

RV techs: share fixes, ask questions and learn from each other.

Join our free Facebook group →



Follow proper safety practices. If in doubt, consult a professional RV technician.